



SWITCH CONTINUITY

		HZ	R	L
FREE				
PUSH		○	○	○
COLOR		Gr	Lb	O

		W	R	L
R		○	○	○
N				
L		○	○	○
COLOR		Gr	Lb	O

		BAT4	Hi
FREE			
PUSH		○	○
COLOR		B/R	●

		HL	Lo	Hi
Lo				
IND		○	○	○
Hi		○	○	○
COLOR		Bu/W	W	●

		Ho	BAT5
FREE			
PUSH		○	○
COLOR		Bl	W/G

		IG	BAT2
OFF			
RUN		○	○
COLOR		Bl	W/Bl

		BAT3	ST	HL
FREE				
PUSH		○	○	○
COLOR		B/R	Y/R	Bu/W

		IG	BAT1	KEY
ON		○	○	KEY ON
OFF				KEY OFF
LOOK				KEY OFF LOOK PIN

IAT SENSOR
MAP SENSOR
NEUTRAL
OIL PRESS

